



SERVICE PRICING

2018

Email: birdiexris@gmail.com

Call or Text: 717.742.5825

Service:	Option:	Price:
Reshaft	Per club Standard	\$20.00
Epoxy/ Grip install	Per club Assembly	\$10.00
	Per Club Bore-Through	\$18.00
"reshaft"	Set of 8	\$135.00
	Set of 3 woods/ hybrids	\$50.00
Disassembly:	Broken Shaft Removal	\$15.00
Remove club head	Standard Disassembly	\$12.00
	Save OEM Adapter	\$18.00
remove club head	Set of 8 Irons	\$85.00
Gripping:	Install Grip	\$2.00
	Save Grip	\$5.00
	Pure Grip Install	\$1.00
Misc services:		
Client provided parts	Per Club (assembly w/ client provided components)	\$15.00
	Replace ferrule w/o removal (one size only)	\$5.00
Shaft Alignment:	Per Club FLO	\$6.00
	Tip/ Butt trim and Prep	\$4.50
Club Lengths: Does not include grip save	Lengthen shaft (up to 1")	\$6.00
	shorten	\$3.50
Bend Loft/Lie	Per Club	\$5.00
Pureing:**	With select shaft purchase	\$15.50
per shaft	New Un-Cut shaft non-Select	\$33.00
	Cut shaft	\$38.00
	Includes disassemble and re-assemble	\$60.00
Club Physical:	Each Club:	\$5.00
Length, swingweight		
lie, loft, frequency,		
Total weight		

****Certified Players' Club – great for gearheads, tournament players, or those looking for a major equipment overhaul. Flat fee to join \$400.00. Members get up to 25% off Fujikura and ProjectX/True Temper components. 10% off all other components and 15% on services (excluding SST Pure). Includes one ½ hour launch monitor session every month in season (Apr1 – Sept 30 by appointment) and includes full set club physical on season start and end. Club expires 12 months from purchase date. Call or email with questions or for more detailed information or if you're just wondering how it could benefit you.

Discounts applied (with valid ID): 10% Student – First Responder – Fire – Police / 15% US Military

**SST Pure services are sent out. May take up to 7 business days.

*Club owner assumes responsibility on lie/loft breakage. I try to inspect every club thoroughly for damage beforehand, but older clubs may have undetectable issues or damage from normal use that may cause failure.